

ALL INDIA INSTITUTE OF MEDICAL SCIENCES
ENGINEERING SERVICES DEPARTMENT
Eastern & Western Campus

1

Sub: Checking of Ceiling Plaster/Sun Shade

It has been observed that areas susceptible to seepage/dampness there are chances of ceiling chunks/plaster falling in long run. As the toilet/ kitchen area of individual units are not always available for inspection by Engineering Services Department. Therefore It is requested that in case the allottee/ occupant finds any noticeable crack/clipping/withering in the ceiling plaster, it should be immediately brought in notice of JE/AE for urgent & immediate remedial measures. This would help in avoiding any mishap on account of falling plaster/ chunk.

Active co-operation is solicited.


(ER K.D. BISWAL)
ASSISTANT ENGINEER-II
Asstt. Engineer (Civil)
A.I.I.M.S., New Delhi

1. Er. Dinesh J.E.(E.Campus)
Ext.4337, Mob. 9868397872

1. Er. Sanjay Jain J.E.(W.Campus)
Ext.3372, Mob. 9868397875

2. ER.K.D.BISWAL, A.E.(E.Campus)
Ext.4973, Mob. 9868397872

2.ER. SUNIL KUMAR, A.E.(W.Campus)
Ext.4771, Mob. 9868397878

Distribution:

1. CI,CII,DII,E,F,I & G type qtrs.of E.Campus & W.Campus at AIIMS.

Copy to: 1. Superintending Engineer } For Information please.
 2. Executive Engineer-II(Civil) } For Information please.