

अखिल भारतीय आयुर्विज्ञान संस्थान केंद्रीय कार्यशाला

अंसारी नगर, नई दिल्ली -110029

दिनांक: 27.02.2021

विषय: पंचर फ्रीजर बॉक्स वाले रेफ्रिजरेटर की मरम्मत के बारे में।

विभिन्न विभागों / अनुभागों / केंद्रों द्वारा केंद्रीय कार्यशाला में भेजे गए रेफ्रिजरेटर की मरम्मत के दौरान, कई मामलों में यह देखा गया है कि फ्रीजर बॉक्स में जमी बर्फ को हटाने के लिए किसी तेज नोक वाले सामान का उपयोग करने के कारण फ्रीजर बॉक्स में छेद हो गया था। एक छिद्रित फ्रीजर बॉक्स से न केवल गैस निकल जाती है, बल्कि इससे नमी गैस चार्जिंग लाइन में प्रवेश भी कर जाती है, जिससे आगे कंडेनसर लाइन और कंप्रेसर को नुकसान पहुंचता है।

चूंकि पंचर फ्रीजर बॉक्स फ्रिज में कई समस्याओं का कारण बनता है और केंद्रीय कार्यशाला में फ्रिज की ऐसी जटिल समस्याओं की मरम्मत के लिए कोई व्यवस्था नहीं है, इसलिए विभागों / अन्भागों / केंद्रों को ऐसे फ्रिज की मरम्मत किसी बाहरी फर्म से करवाने की आवश्यकता होगी।

उपरोक्त तथ्यों के मद्देनजर, सभी विभागों / अनुभागों / केंद्रों के ऐसे अधिकारियों को जिनके पास फ्रिज का प्रभार है उन्हें अपने-अपने विभागों में फ्रिज को डिफ्रॉस्ट करने के लिए निर्माता कंपनी दवारा दी गयी उचित विधि का उपयोग करने की सलाह दी जाती है।

डा० गंगाँ प्रसाद/Dr. Ganga Pra. .

आचार्य संवेदनाहरण विद्यान/Prof of Anaesthesions.

संकाय समन्त्रक/Faculty Co-ordinator संकाय समन्वयक केन्द्रीय कार्यज्ञाला/Central Workshop केंद्रीय कार्यशालाबीय भारतीय आसुर्विज्ञान संस्थान/A. । 🗀 🗈 न्दं दिल्ली-110029/New Delhi-110029

1) सभी विभागाध्यक्ष

2) सभी सिस्टर इन्चार्ज / एएनएस / डीएनएस

3) सभी तकनीशियन / तकनीकी अधिकारी

4) सभी स्टोर अधिकारी

pr. uploced to Mr. Savjew Keman homs website Ph. Aman Lot? Ph. Aman 113)21

Chky7187

म्ख्य तकनीकी अधिकारी

नुख्य तकनीको अधिकारी

Chief Technical Officer जेन्द्रीय कार्यसाला/Central Warkshop

अखिल भारतीय आयुर्विज्ञान संस्थान All India Institute : Medical Sciences

नाई विल्ली-29 : Deihi-110029

(कालू राम)

प्राप्त किया / RECEIVEL) कम्प्यूटर गुविधा / Computer Facility

ALL INDIA INSTITUTE OF MEDICAL SCIENCES

Central Workshop Ansari Nagar, New Delhi-110029

Dated: 27.02.2021

Subject: Repair of refrigerators with punctured freezer box - Regarding

During the repairs of refrigerators sent by various Departments/Sections/Centers to Central Workshop, in many cases it has been observed that the freezer box was punctured due to using some sharp tip object to remove the frost from the freezer box. A punctured freezer box not only drains the refrigerant gas, but it also causes moisture to enter into the gas charging line, which can further cause damage to the condenser line and the compressor.

Since the punctured freezer box leads to multiple problems in the fridge and there is no arrangement for repair of such complex fault of fridge in Central Workshop therefore the Departments/Sections/Centers will be required to get such fridge repaired from outside firm which deals in such problems.

In view of the above facts all the officers having charge of the fridges of their respective Departments/Sections/Centers are advised herewith to use the proper method, as provided by the manufacturer company, for defrosting the fridge.

(Kalu Ram)

2816 गंगा प्रसाद/Dr. Ganga Presed 21- आंचार्य संवेदनाहरण विज्ञान/Prof of Anaesthesiology

Faculty Coordinator संकाय समन्वयक/Faculty Co-ordinator केन्द्रीय कार्यशाला/Central Workshop

Central Workshop अखिल भारतीय आयुर्विज्ञान संस्थान/A.I.I.M.S. नई दिस्ती-110029/New Delhi-110029

1) All Head of Departments

2) All Sr. In charge/ANS/DNS

3) All Technicians/ Technical Officer

4) All store officers

Chief Technical Officer

KALU RAM
मुख्य तकरीको अधिकारी
Chief Technical Officer
ज्दीय कार्यशाला/Central Workship
अखिल भारतीय आयुक्तिल संस्थान
All India Institute of Medical Selenges
मई दिल्ली-29/New Dalhi-110029

pr. uproach to

MINA usobsit:

MINA